

TECHNICAL BULLETIN

No: LTB00319 (ISSUE 1)
02 MAR 2011



CIRCULATE TO: SERVICE ✓ PARTS ✓ WARRANTY ✓ BODY SHOP ✓

SECTION: 501

Exterior A-Pillar Moulding Loose

AFFECTED VEHICLE RANGE:

LR3 (LA)

VIN: 5A000360 - 9A513325
Model Year: 2005 - 2009

LR4 (LA)

VIN: AA510742 - Onwards
Model Year: 2010 - Onwards

CONDITION SUMMARY:

Situation: The exterior A-pillar moulding may become loose. This may be caused by the moulding's retaining clips losing tension.

Action: In the event of a customer concern of the above, refer to the Repair Procedure outlined below to install new A-pillar moulding retaining clips.

PARTS:

LR026343A-pillar retaining clips fitting kit Qty: 1

TOOLS:

Refer to Workshop Manual for any required special tools

WARRANTY:



NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.

DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Finisher - windscreen - side - renew	76.43.39	0.10	07	DYC500020

Normal Warranty policies and procedures apply

REPAIR PROCEDURE

INSTALL A-PILLAR RETAINING CLIPS

1. Refer to Workshop Manual, section 501-08: Exterior Trim and Ornamentation, and remove the affected A-pillar moulding.
2. Install new retaining clips.
3. Refer to Workshop Manual, section 501-08: Exterior Trim and Ornamentation, and install the affected A-pillar moulding.

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.