543544

ROAD

GS3 YRA

01282772125 Office -58202 P21880 610 R17353 Use Only SMW PLAN 8 **Warranty Wise** Plan Number Date Repairer's Assessment 16/03/2011 **VEHICLE DETAILS** FAO SHIELDS LANDROVER Name & TOMLIN Planholder **Address** 1000 KENNISHEAD LANDROVER of Repairer Make GLASGOW DISCOVERY Model Tel 0141 876 1001 A15DPT Reg No Fax 0141 876 1188 Vat Reg No 624 1766 45 DETAILS OF REPAIR REQUEST 579 Current Mileage Fuel Type DIESEL SALL AAA 175A 318300 Vin / Chassis No Date of Breakdown 16/03/2011 Country of Origin UK 1543.80 LR 00 59 61 KIT FUEL INSECTION Name of Faulty Part 288.72 x6 INSECTOR PIPES Part Numbers and L1331261 RING Individual Prices TUBEN INSECTION check fault codes , checked DATA log MISFIRE Description of Repair Showing faulty strip down and check wiring to all injectors, carry out disconnect feed to injectors Net a NO6 mistere worse compression test: Please State Reason for Part Failure & Provide any Diagnostic Printouts

Parts £ 1289 31 Labour £ 935 00 Hours 1/ 00 Totals £ 282430 Estimated Cost of Repair (ex Vat) Inc Recovery & Car Hire Recovery £ Car Hire £ NB: Estimated costs may differ from the final Authorised Amount

2 INSECTORS SLIGHT LEAK UP PAST SEAL

LEAKING UP PAST SEAL

& INSECTORS

2 INSECTORS

Reason for Part Failure

Name CAROLINE DOWNIE Date 16:03:11 Repairer Sign After completing this assessment form (fully) please fax/post to: Warranty Wise (Repairs Department),

Please take your instructions from the vehicle owner regarding authorisation for the stripdown and to confirm the payment of your invoice. Do not complete any repairs until Warrantywise have decided whether (or not) an Independent Inspection is required and issued authorisation.

Fraud is a serious crime and anyone attempting to make a fraudulent request will be prosecuted.

Ribble Court, 1 Mead Way, Padiham, Lancashire. Tel: 0845 293 2570. Fax: 0128 277 2125

This request for repair is made by the vehicle owner, subject to Warrantywise plan limits, exclusions and terms and conditions. The completion of this form does not guarantee authorisation or any payment from Warrantywise. However, failure to complete and sign this form will result in any decision being delayed.

01282772125

## Warrantywise

www.warrantywise.co.uk info@warrantywise.co.uk

Warrantywise Ribble Court 1 Mead Way Padiham, Burnley Lancashire BB12 7NG

Mr Tomlin 22 Drummond Way **Newton Mearns** GLASGOW **G77 6XW** 

Date 18/03/2011

Reference Number 543544

Repair Authority Number NOT

1

Vehicle Reg No A15DPT

Office

Use Only P21880 R17353

Dear Mr Tomlin

## RE: Your Recent Warranty Request for Repairs.

I regret to advise you that after careful consideration of your request, I am unable to accept and authorise your request for payment towards the cost of repairing or replacing the required parts of your vehicle.

The reason we have declined your request for reparis on this occasion is because your repairer has confirmed that 2 fuel injectors are leaking past the seal and 2 fuel injectors have a slight leak and 2 fuel injectors have failed. however, the provided diagnostic print out only confirms 2 injectors are showing lower efficiency. These would not be considered to be suffering from any failure as defined, but would suggest they are suffering from normal in service wear and deterioration. This plan does not include parts which have not suffered a failure (as defined) and worn out parts. Please refer to the plan document for full terms and conditions

Your Warrantywise Plan, like all plans of this type contains certain conditions and exclusions. I should explain that warranties do not cover every eventuality that may befall the customer, as to do so would make the cost of the cover prohibitively expensive. The level of cover provided is reflected in the charges you have paid and detailed in the warranty documentation you have received.

If for any reason you wish to dispute the decision made, please write with full supporting documentation to the address above.

Yours sincerely

Warrantywise Repairs Department